

**UNISYS**

DATE: January 16, 1996  
 TO: G. Kramer/311  
 FROM: K. Sahu/300.1 KS  
 SUBJECT: Radiation Report on: 28C256  
           Project: AXAF/Gulton  
           Control #: 14509  
           Job #: ER61108  
           Project part #: 28C256EFY-25

PPM-95-187

cc: T. Canales/Gulton  
 R. Bagget/MSFC  
 M. A. Dooley/TRW  
 A. Sharma/311  
 OFA Library/300.1

A radiation evaluation was performed on 28C256 (EEPROM) to determine the total dose tolerance of these parts. A brief summary of the test results is provided below. For detailed information, refer to Tables I through IV and Figure 1.

The total dose testing was performed using a Co<sup>60</sup> gamma ray source. During the radiation testing, five parts were irradiated under bias (see Figure 1 for bias configuration) and one part was used as a control sample. The total dose radiation levels were 1, 2, 3, 4, 5, 6, 7, 8, 9 and 10 krad\*. The dose rate was between 0.50 and 0.59 krad/hour (see Table II for radiation schedule). After each radiation exposure, parts were electrically tested according to the test conditions and the specification limits\*\* listed in Table III. The electrical measurements included six initial (pre-rad) functional tests at 10 MHz: These functional tests were WRITE/READ ZEROES, WRITE/READ ONES and WRITE/READ CHECKERBOARD with Vcc = 4.5 V, Vil = 0.0 V and Vih = 4.5 V and the same three tests with Vcc = 5.5 V, Vil = 0.0 V and Vih = 5.5 V. After the first (1 krad) irradiation, six additional functional tests were added. These were WRITE/READ ZEROES, WRITE/READ ONES and WRITE/READ CHECKERBOARD with Vcc = 5.0 V, Vil = 0.0 V and Vih = 5.0 V, and Three READ CHECKERBOARD tests, one with Vcc = 4.5 V, Vil = 0.0 V and Vih = 4.5 V, one with Vcc = 5.0 V, Vil = 0.0 V and Vih = 5.0 V and one with Vcc = 5.5 V, vil = 0.0 V and Vih = 5.5 V.

All parts passed all initial electrical parametric and functional tests.

All irradiated parts passed all electrical parametric and functional tests up to and including the 7 krad irradiation level.

After the 8 krad irradiation, S/N 61 failed Functional Test # 1 (READ CHECKERBOARD @ Vcc = 4.5 V), #2 (READ CHECKERBOARD @ Vcc = 5.0 V) and #3 (READ CHECKERBOARD @ Vcc = 5.5 V). This indicates that the checkerboard pattern written into the part before the 8 krad irradiation was corrupted during the irradiation. In addition, SN 61, 63 and 64 failed Functional Test # 6 (WRITE/READ CHKBD @ Vcc = 4.5 V), #9 (WRITE/READ CHKBD @ Vcc = 5.0 V) and #12 (WRITE/READ CHKBD @ Vcc = 5.5 V). These results, i.e., failures in the WRITE/READ CHKBD test, but not in the WRITE/READ ZEROES or WRITE/READ ONES tests, indicate that the functional failures are pattern-sensitive. The same parts also failed the VOL test.

After annealing for 24 hours at 25°C, no recovery was observed. In addition, after this annealing, S/N 63 and 64 also failed Functional Tests # 1, 2 and 3.

\* The term rads, as used in this document, means rads(silicon). All consecutive annealing times at the same temperature and all radiation levels cited are cumulative.

\*\* These are manufacturer's pre-irradiation data specification limits. No post-irradiation limits were provided by the manufacturer at the time these tests were performed.

After annealing for an additional 144 hours at 25°C, for a cumulative total of 168 hours, no recovery was observed.

After annealing for an additional 144 hours, for a cumulative total of 336 hours at 25°C, no recovery was observed.

After the 9 krad irradiation, the same failures in VOL and the same functional failures continued to be observed. In addition, S/N 63 and 64 failed Functional Tests # 1, 2 and 3, and S/N 62, 63, 64 and 65 failed Functional Test # 5 (WRITE/READ ONES).

After the 10 krad irradiation, the same failures in VOL and the same functional failures continued to be observed. In addition, all irradiated parts failed Functional Test # 5, 6, 8 (WRITE/READ ONES) and 9, S/N 64 failed Functional Test #4 (WRITE/READ ZEROES), S/N 62 failed Functional Test # 4 and S/N 62, 63, 64 and 65 failed Functional Test # 11 (WRITE/READ ONES). S/N 62 failed the VOL test and S/N 64 exceeded the maximum specification limit of 350  $\mu$ A for both ICCL3 and ICCH3, with readings of 574  $\mu$ A for both parameters.

After annealing for 312 hours at 25°C, the following changes in the functional test results were observed: S/N 61 passed Functional Test # 8, S/N 62 failed Functional Tests # 1, 2, 3, 7 and 10, S/N 63 showed no change, S/N 64 failed Functional Test # 4 and S/N 65 passed Functional Test # 9. No recovery was observed in any of the parametric tests.

After annealing for 168 hours at 100°C, S/N 62 and 64 failed Functional Tests # 1, 2, 3, 6, 9 and 12. All other irradiated parts passed all functional tests. No rebound effects were observed.

Table IV provides a summary of the functional test results and the mean and standard deviation values for each parameter after each irradiation exposure and annealing step.

Any further details about this evaluation can be obtained upon request. If you have any questions, please call me at (301) 731-8954.


---

#### ADVISORY ON THE USE OF THIS DOCUMENT

The information contained in this document has been developed solely for the purpose of providing general guidance to employees of the Goddard Space Flight Center (GSFC). This document may be distributed outside GSFC only as a courtesy to other government agencies and contractors. Any distribution of this document, or application or use of the information contained herein, is expressly conditional upon, and is subject to, the following understandings and limitations:

- (a) The information was developed for general guidance only and is subject to change at any time;
- (b) The information was developed under unique GSFC laboratory conditions which may differ substantially from outside conditions;
- (c) GSFC does not warrant the accuracy of the information when applied or used under other than unique GSFC laboratory conditions;
- (d) The information should not be construed as a representation of product performance by either GSFC or the manufacturer;
- (e) Neither the United States government nor any person acting on behalf of the United States government assumes any liability resulting from the application or use of the information.

Figure 1. Radiation Bias Circuit for 28C256



- 1)  $V_{CC} = +5.0 \text{ VDC} \pm 0.5 \text{ VDC}$ ,  $V_{CC}/2 = 2.5 \text{ VDC} \pm 0.25 \text{ VDC}$
- 2) All resistors  $R = \cancel{2.0K} \text{ Ohms} \pm 10\%$ , 1/4 W  
3.3K

TABLE I. Part Information

Generic Part Number:	28C256*
AXAF/Gulton Part Number	28C256EFY-25
AXAF/Gulton Control Number:	14509
Charge Number:	ER61108
Manufacturer:	SEI
Lot Date Code (LDC):	9543
Quantity Tested:	6
Serial Number of Control Samples:	60
Serial Numbers of Radiation Samples:	61, 62, 63, 64, 65
Part Function:	EEPROM
Part Technology:	CMOS
Package Style:	32-pin Flatpack
Test Equipment:	S-50
Engineer:	K. Kim

\* No radiation tolerance/hardness was guaranteed by the manufacturer for this part.

TABLE II. Radiation Schedule for 28C256

EVENT .....	DATE
1) INITIAL ELECTRICAL MEASUREMENTS.....	11/16/95
2) 1 KRAD IRRADIATION (0.59 KRADS/HOUR) .....	11/16/95
POST-1 KRAD ELECTRICAL MEASUREMENT.....	11/17/95
3) 2 KRAD IRRADIATION (0.59 KRADS/HOUR) .....	11/17/95
POST-2 KRAD ELECTRICAL MEASUREMENT.....	11/21/95
4) 3 KRAD IRRADIATION (0.59 KRADS/HOUR) .....	11/21/95
POST-3 KRAD ELECTRICAL MEASUREMENT.....	11/22/95
5) 4 KRAD IRRADIATION (0.59 KRADS/HOUR) .....	11/27/95
POST-4 KRAD ELECTRICAL MEASUREMENT.....	11/28/95
6) 5 KRAD IRRADIATION (0.59 KRADS/HOUR) .....	11/28/95
POST-5 KRAD ELECTRICAL MEASUREMENT.....	11/29/95
7) 6 KRAD IRRADIATION (0.59 KRADS/HOUR) .....	11/29/95
POST-6 KRAD ELECTRICAL MEASUREMENT.....	11/30/95
8) 7 KRAD IRRADIATION (0.59 KRADS/HOUR) .....	11/30/95
POST-7 KRAD ELECTRICAL MEASUREMENT.....	12/01/95
9) 8 KRAD IRRADIATION (0.59 KRADS/HOUR) .....	12/03/95
POST-8 KRAD ELECTRICAL MEASUREMENT.....	12/04/95
10) 24-HOUR ANNEALING @25°C.....	12/04/95
POST-24 HOUR ANNEAL ELECTRICAL MEASUREMENT .....	12/05/95
11) 168-HOUR ANNEALING @25°C.....	12/05/95
POST-168 HOUR ANNEAL ELECTRICAL MEASUREMENT .....	12/11/95
12) 336-HOUR ANNEALING @25°C.....	12/11/95
POST-336 HOUR ANNEAL ELECTRICAL MEASUREMENT .....	12/18/95
13) 9 KRAD IRRADIATION (0.59 KRADS/HOUR) .....	12/18/95
POST-9 KRAD ELECTRICAL MEASUREMENT.....	12/19/95
14) 10 KRAD IRRADIATION (0.50 KRADS/HOUR) .....	12/19/95
POST-10 KRAD ELECTRICAL MEASUREMENT.....	12/20/95
15) 312-HOUR ANNEALING @25°C.....	12/21/95
POST-312 HOUR ANNEAL ELECTRICAL MEASUREMENT .....	01/02/96
16) 192-HOUR ANNEALING @ 100°C.....	01/03/96
POST-192-HOUR ANNEAL ELECTRICAL MEASUREMENT.....	01/11/96

PARTS WERE IRRADIATED AND ANNEALED UNDER BIAS; SEE FIGURE 1.

Table III. Electrical Characteristics of 28C256

PVT OR INITIAL EM'S FUNCTIONAL TESTS PERFORMED									
PARAMETER	VCC	VIL	VIH	PATTERN	CONDITIONS	PINS	LIMITS		
FUNCT # 1	4.5V	0.0V	4.5V	WR/RD ZEROS	FREQ=0.5 MHZ	I/O'S	VOL	<1.0V	VOH >2.0V
FUNCT # 2	4.5V	0.0V	4.5V	WR/RD ONES	FREQ=0.5 MHZ	I/O'S	VOL	<1.0V	VOH >2.0V
FUNCT # 3	4.5V	0.0V	4.5V	WR/RD CHKBD	FREQ=0.5 MHZ	I/O'S	VOL	<1.0V	VOH >2.0V
FUNCT # 4	5.5V	0.0V	5.5V	WR/RD ZEROS	FREQ=0.5 MHZ	I/O'S	VOL	<1.0V	VOH >2.0V
FUNCT # 5	5.5V	0.0V	5.5V	WR/RD ONES	FREQ=0.5 MHZ	I/O'S	VOL	<1.0V	VOH >2.0V
FUNCT # 6	5.5V	0.0V	5.5V	WR/RD CHKBD	FREQ=0.5 MHZ	I/O'S	VOL	<1.0V	VOH >2.0V
POST RADIATION/ANNEALING EM'S FUNCTIONAL TESTS PERFORMED									
PARAMETER	VCC	VIL	VIH	PATTERN	CONDITIONS	PINS	LIMITS		
FUNCT # 1	4.5V	0.0V	4.5V	READ CHKBD	FREQ=0.5 MHZ	I/O'S	VOL	<1.0V	VOH >2.0V
FUNCT # 2	5.5V	0.0V	5.5V	READ CHKBD	FREQ=0.5 MHZ	I/O'S	VOL	<1.0V	VOH >2.0V
FUNCT # 3	5.5V	0.0V	5.5V	READ CHKBD	FREQ=0.5 MHZ	I/O'S	VOL	<1.0V	VOH >2.0V
FUNCT # 4	4.5V	0.0V	4.5V	WR/RD ZEROS	FREQ=0.5 MHZ	I/O'S	VOL	<1.0V	VOH >2.0V
FUNCT # 5	4.5V	0.0V	4.5V	WR/RD ONES	FREQ=0.5 MHZ	I/O'S	VOL	<1.0V	VOH >2.0V
FUNCT # 6	4.5V	0.0V	4.5V	WR/RD CHKBD	FREQ=0.5 MHZ	I/O'S	VOL	<1.0V	VOH >2.0V
FUNCT # 7	5.5V	0.0V	5.5V	WR/RD ZEROS	FREQ=0.5 MHZ	I/O'S	VOL	<1.0V	VOH >2.0V
FUNCT # 8	5.5V	0.0V	5.5V	WR/RD ONES	FREQ=0.5 MHZ	I/O'S	VOL	<1.0V	VOH >2.0V
FUNCT # 9	5.5V	0.0V	5.5V	WR/RD CHKBD	FREQ=0.5 MHZ	I/O'S	VOL	<1.0V	VOH >2.0V
FUNCT # 10	5.5V	0.0V	5.5V	WR/RD ZEROS	FREQ=0.5 MHZ	I/O'S	VOL	<1.0V	VOH >2.0V
FUNCT # 11	5.5V	0.0V	5.5V	WR/RD ONES	FREQ=0.5 MHZ	I/O'S	VOL	<1.0V	VOH >2.0V
FUNCT # 12	5.5V	0.0V	5.5V	WR/RD CHKBD	FREQ=0.5 MHZ	I/O'S	VOL	<1.0V	VOH >2.0V
DC PARAMETRIC TESTS PERFORMED									
PARAMETER	VCC	VIL	VIH	CONDITIONS	PINS	LIMITS @ +25C			
VOL	4.5V	0.8V	2.0V	LOAD = +2.1MA	OUTS	> 0.0V	< 0.45V		
VOH	4.5V	0.8V	2.0V	LOAD = -400UA	OUTS	> 2.4V	< 4.5V		
IIL	5.5V	0.1V	5.5V	TSTV = +0.1V	INS	> -100NA	< +100NA		
IIH	5.5V	0.0V	5.5V	TSTV = +5.5V	INS	> -100NA	< +100NA		
IOZL	5.5V	0.1V	5.5V	TSTV = +0.1V	OUTS	> -500NA	< +500NA		
IOZH	5.5V	0.0V	5.5V	TSTV = +5.5V	OUTS	> -500NA	< +500NA		
IOE	5.5V	0.0V	5.5V	TSTV = +13.0V	OE	> -10UA	< +100UA		
ICCL1	5.5V	0.0V	5.5V	FREQ = 5.0MHZ	VCC	> 0MA	< 80MA		
ICCL2	5.5V	0.8V	2.0V	CE=VIH, VI=OE=VIL	VCC	> 0MA	< 3MA		
ICCH2	5.5V	0.8V	2.0V	CE=VIH, VI=VIL	VCC	> 0MA	< 3MA		
ICCL3	5.5V	0.0V	5.2V	CE=VIH, VI=VIL	VCC	> 0UA	< 350UA		
ICCH3	5.5V	0.0V	5.2V	CE=VIH, VI=VIH	VCC	> 0UA	< 350UA		
SPECIAL COMMENTS AND EXCEPTIONS									
(1) VIL & VIH TESTS PERFORMED WITHIN VOL & VOH TEST GO/NOGO.									
(2) TEST NOT PERFORMED : CIN & COUT DYNAMIC CAPACITANCE TESTS.									

TABLE IV: Summary of Functional Measurements after Total Dose Exposures and Annealing for 28C256 /1

#	# Functional Tests /2	Pattern	Initial	# Functional Tests /3, 4	Pattern	Total Dose Exposure (TDE) (krads)				
						1	2	3	4	5
1	V <sub>cc</sub> =4.5V, V <sub>il</sub> =0.0V, V <sub>ih</sub> =4.5V, Freq.=0.5MHz	WR/RD 0's	P	1 V <sub>cc</sub> =4.5V, V <sub>il</sub> =0.0V, V <sub>ih</sub> =4.5V, Freq.=0.5MHz	READ CHKBD	P	P	P	P	P
2	V <sub>cc</sub> =4.5V, V <sub>il</sub> =0.0V, V <sub>ih</sub> =4.5V, Freq.=0.5MHz	WR/RD 1's	P	2 V <sub>cc</sub> =5.0V, V <sub>il</sub> =0.0V, V <sub>ih</sub> =5.0V, Freq.=0.5MHz	READ CHKBD	P	P	P	P	P
3	V <sub>cc</sub> =4.5V, V <sub>il</sub> =0.0V, V <sub>ih</sub> =4.5V, Freq.=0.5MHz	WR/RD CHKBD	P	3 V <sub>cc</sub> =5.5V, V <sub>il</sub> =0.0V, V <sub>ih</sub> =5.5V, Freq.=0.5MHz	READ CHKBD	P	P	P	P	P
4	V <sub>cc</sub> =5.5V, V <sub>il</sub> =0.0V, V <sub>ih</sub> =5.5V, Freq.=0.5MHz	WR/RD 0's	P	4 V <sub>cc</sub> =4.5V, V <sub>il</sub> =0.0V, V <sub>ih</sub> =4.5V, Freq.=0.5MHz	WR/RD 0's	P	P	P	P	P
5	V <sub>cc</sub> =5.5V, V <sub>il</sub> =0.0V, V <sub>ih</sub> =5.5V, Freq.=0.5MHz	WR/RD 1's	P	5 V <sub>cc</sub> =4.5V, V <sub>il</sub> =0.0V, V <sub>ih</sub> =4.5V, Freq.=0.5MHz	WR/RD 1's	P	P	P	P	P
6	V <sub>cc</sub> =5.5V, V <sub>il</sub> =0.0V, V <sub>ih</sub> =5.5V, Freq.=0.5MHz	WR/RD CHKBD	P	6 V <sub>cc</sub> =4.5V, V <sub>il</sub> =0.0V, V <sub>ih</sub> =4.5V, Freq.=0.5MHz	WR/RD CHKBD	P	P	P	P	P
7				7 V <sub>cc</sub> =5.0V, V <sub>il</sub> =0.0V, V <sub>ih</sub> =5.0V, Freq.=0.5MHz	WR/RD 0's	P	P	P	P	P
8				8 V <sub>cc</sub> =5.0V, V <sub>il</sub> =0.0V, V <sub>ih</sub> =5.0V, Freq.=0.5MHz	WR/RD 1's	P	P	P	P	P
9				9 V <sub>cc</sub> =5.0V, V <sub>il</sub> =0.0V, V <sub>ih</sub> =5.0V, Freq.=0.5MHz	WR/RD CHKBD	P	P	P	P	P
10				10 V <sub>cc</sub> =5.5V, V <sub>il</sub> =0.0V, V <sub>ih</sub> =5.5V, Freq.=0.5MHz	WR/RD 0's	P	P	P	P	P
11				11 V <sub>cc</sub> =5.5V, V <sub>il</sub> =0.0V, V <sub>ih</sub> =5.5V, Freq.=0.5MHz	WR/RD 1's	P	P	P	P	P
12				12 V <sub>cc</sub> =5.5V, V <sub>il</sub> =0.0V, V <sub>ih</sub> =5.5V, Freq.=0.5MHz	WR/RD CHKBD	P	P	P	P	P

Notes:

- 1/ The mean and standard deviation values were calculated over the five parts irradiated in this testing.
- 2/ The control sample remained constant throughout the testing and is not included in this table.
- 3/ "P" indicates that all parts passed this test at this irradiation or annealing level. "F" indicates that all parts failed this test at this irradiation or annealing level. "nPmF" indicates that n parts passed and m parts failed this test at this irradiation or annealing level.
- 4/ Prior to the first irradiation, a checkerboard pattern was written into the parts to be irradiated.
- 5/ After the start of irradiation, the test program was modified to include additional tests (see Table III).
- 6/ After the first (1 krad) irradiation, a modified set of functional tests was used (see text).
- 7/ These are manufacturer's pre-irradiation data sheet specification limits. No post-irradiation limits were provided by the manufacturer at the time these tests were performed.





TABLE IV(Cont'd.): Summary of Parametric Measurements after Total Dose Exposures and Annealing for 28C256 /1

#	Parameters	Units	Spec. Lim./2, 5 min max	Total Dose Exposure (TDE) (krads)																							
				Initial		1		2		3		4		5		6		7		8							
				mean	sd	mean	sd	mean	sd	mean	sd	mean	sd	mean	sd	mean	sd	mean	sd	mean	sd	mean	sd				
1	VOL/2	mV	0 450	84.0	1.2	83.8	1.5	84.0	1.5	84.2	1.6	84.4	1.7	84.0	2.2	84.1	1.9	84.2	1.5	84.2	1.5	3P3F					
2	VOH	V	2.4 4.5	3.66	.02	3.66	.02	3.66	.02	3.67	.02	3.67	.02	3.67	.01	3.67	.02	3.68	.02	3.68	.02	3.68	.02				
3	IIL	µA	-10 10	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0				
4	IIH	µA	-10 10	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0				
5	IOZL	µA	-10 10	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0				
6	IOZH	µA	-10 10	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0				
7	IOE	µA	-10 100	7.90	.30	8.03	.30	8.10	.30	8.15	.30	8.17	.29	8.25	.30	8.31	.30	8.38	.30	8.44	.27						
8	ICCI	mA	0 80	7.44	.22	7.60	.19	7.57	.22	7.65	.23	7.66	.19	7.72	.24	7.79	.19	7.87	.18	7.29	.74						
9	ICCL2	mA	0 3	1.78	.07	1.74	.06	1.73	.07	1.70	.07	1.67	.06	1.66	.07	1.64	.06	1.64	.08	1.65	.09						
10	ICCH2	mA	0 3	1.78	.07	1.74	.07	1.73	.07	1.71	.07	1.68	.06	1.67	.06	1.65	.06	1.63	.07	1.64	.10						
11	ICCL3	µA	0 350	33.6	4.9	35.2	7.7	40.4	7.1	37.2	4.0	38.8	6.0	42.0	7.5	31.8	4.0	52.8	27	77.2	72						
12	ICCH3	µA	0 350	40.4	7.1	37.2	4.0	30.0	0	35.4	4.9	40.2	9.3	33.4	9.9	40.6	9.4	56.2	30	79.0	71						

Notes:

- 1/ The mean and standard deviation values were calculated over the five parts irradiated in this testing.
- 2/ "P" indicates that all parts passed this test at this irradiation or annealing level. "F" indicates that all parts failed this test at this irradiation or annealing level. "nPmF" indicates that n parts passed and m parts failed this test at this irradiation or annealing level.
- 3/ Prior to the first irradiation, a checkerboard pattern was written into the parts to be irradiated.
- 4/ After the start of irradiation, the test program was modified to include additional tests (see Table III).
- 4/ After the first (1 krad) irradiation, a modified set of functional tests was used (see text).
- 5/ These are manufacturer's pre-irradiation data sheet specification limits. No post-irradiation limits were provided by the manufacturer at the time these tests were performed.

TABLE IV(Cont'd.): Summary of Parametric Measurements after Total Dose Exposures and Annealing for 28C256 /1

#	Parameters	Units	min	max	Spec. Lim./2, 5	Annealing												TDE (krads)					
						24 hrs. @ 25°C		168 hrs. @ 25°C		336 hrs. @ 25°C		9		10		312 hrs. @ 25°C		192 hrs. @ 100°C					
						mean	sd	mean	sd	mean	sd	mean	sd	mean	sd	mean	sd	mean	sd				
1	VOL	mV	0	450		3P3F	3P3F	3P3F	3P3F	3P3F	3P3F	2P4F	1P4F	3P2F									
2	VOH	V	2.4	4.5		3.68	3.68	3.68	3.68	3.68	3.68	3.68	3.67	3.58	.04								
3	IIL	µA	-10	10		0	0	0	0	0	0	0	0	0	0	0							
4	IHH	µA	-10	10		0	0	0	0	0	0	0	0	0	0	0							
5	IOZL	µA	-10	10		0	0	0	0	0	0	0	0	0	0	0							
6	IOZH	µA	-10	10		0	0	0	0	0	0	0	0	0	0	0							
7	IOE	µA	-10	100		8.45	8.45	8.45	8.45	8.45	8.45	8.42	8.45	8.10	.24								
8	ICCI	mA	0	80		7.28	7.28	7.28	7.28	7.6	6.19	2.7	7.26	7.23	.69								
9	ICCL2	mA	0	3		1.64	1.64	1.64	1.64	.10	1.65	.14	1.71	1.57	.09								
10	ICCH2	mA	0	3		1.65	1.65	1.65	1.65	.10	1.65	.15	1.72	1.57	.08								
11	ICCL3	µA	0	350		77.2	77.2	73	77.2	73	107	131	185	194	27								
12	ICCH3	µA	0	350		78.8	78.8	72	78.8	72	109	121	189	225	23								

Notes:

- 1/ The mean and standard deviation values were calculated over the five parts irradiated in this testing. The control sample remained constant throughout the testing and is not included in this table.
- 2/ "P" indicates that all parts passed this test at this irradiation or annealing level. "F" indicates that all parts failed this test at this irradiation or annealing level. "nPmF" indicates that n parts passed and m parts failed this test at this irradiation or annealing level.
- 3/ Prior to the first irradiation, a checkerboard pattern was written into the parts to be irradiated. After the start of irradiation, the test program was modified to include additional tests (see Table III).
- 4/ After the first (1 krad) irradiation, a modified set of functional tests was used (see text).
- 5/ These are manufacturer's pre-irradiation data sheet specification limits. No post-irradiation limits were provided by the manufacturer at the time these tests were performed.